

Power Distribution

# Redundant Power Center

**PD-4A**

|                                      |   |
|--------------------------------------|---|
| AC Input                             | 100~240 VAC (50Hz or 60Hz)<br>AC input outlet: Two AC inputs & Two Power Switches                           |
| DC Backup Input                      | One DC 12V/25A<br>supports non-regulated DC 12V output  |
| DC Output                            | 5<br>12V±5%, 5A XLR DC Female Jack x3<br>12V±5%, 10A XLR DC Female Jack x1<br>(share of two XLR DC Jack)    |
| Max. Power Rating                    | 360W  |
| DC Overload                          | DC overload protection, auto-recovery<br>fuses on each DC output terminal                                   |
| AC Overload                          | non-recovery fuse on the AC input outlet  |
| LED Indicator                        | Green LED: Unit under working condition<br>Red twinkle: AC Input failed<br>1~4 XLR DC outputs LED indicator |
| Power Source Input Select<br>AUTO/AC | Selectable of Auto/AC input switch  |
| Dimension (LxWxH)                    | 484 x 300 x 49 mm   |
| Weight                               | 6.1 kg  |
| Power                                | AC 100-240 VAC<br>DC 12V 300W   |
| Operating Temp. Range                | 0~40 °C   |
| What's in the Box                    | 1 x PD-4A product<br>1 x AC CORD  |